

**JADUAL HARGA BAGI KERJA-KERJA SENGARAAN PENCEGAHAN JANAKUASA TUNGGUSEDIA (GENSET) SELAMA SATU (1) TAHUN DI Uitm PULAU PINANG
KAMPUS PERMATANG PAUH**

NO.	LOKASI	ENJIN	SAIZ	NO. ENJIN / NO. SERIAL ENJIN	ALTERNATOR	SEKALI (1) SERVIS
1	P/E BANGUNAN PERDANA (G1)	CUMMINS	1500KVA	33150553	STAMFORD	SEKALI (1) SERVIS
2	P/E BANGUNAN PERDANA (G2)	CUMMINS	1500KVA	33150379	STAMFORD	SEKALI (1) SERVIS
3	P/E PENGURUSAN HOTEL	PERKINS	600KVA	SGA120000U0390J	STAMFORD	
4	P/E KEJ. MEKANIKAL	PERKINS	400KVA	SGJ060000U1110J	STAMFORD	SEKALI (1) SERVIS
5	BENGKEL MEKANIKAL	PERKINS	175KVA	2614/1500 YD51332 U884651P	STAMFORD	
6	P/E PERPUSTAKAAN	PERKINS	175KVA	2614/1500 YD51332 U884644P	STAMFORD	SEKALI (1) SERVIS
7	P/E DEWAN BESAR	DOOSAN	275KVA	ED10A103208	MARELLI	
8	PUSAT KESIHATAN	IVECO	20KVA	DPS8522A131A	MARELLI	SEKALI (1) SERVIS
9	P/E KOLEJ ZAMRUD	PERKINS	400KVA	SGJ060000U1364J	STAMFORD	
10	P/E KOLEJ BAIDURI	PERKINS	400KVA	SGJ060000U1363J	STAMFORD	SEKALI (1) SERVIS
11	P/E KOLEJ NILAM	DOOSAN	150KVA	EBPOB904885	MARELLI	
12	P/E KOLEJ INTAN	DOOSAN	150KVA	EBPOB90517	MARELLI	SEKALI (1) SERVIS
13	P/E KOLEJ DELIMA	IVECO	250KVA	14897	MARELLI	
14	P/E KOLEJ KIRSTAL (A)	IVECO	250KVA	90256	MARELLI	SEKALI (1) SERVIS
15	P/E KOLEJ KIRSTAL (B)	IVECO	250KVA	13474	MARELLI	